

Version 4.0.20.20



RGS REBAR

Release NOTE – OCTOBER 2023

Bug

- 1. RRCP - 1267 / QG2 – 1880 & QG2 - 1881**
Coupler match property bug has resolved.
- 2. RRCP - 1262**
Range blocks missing bug has resolved.
- 3. RRCP - 1254 / QG2 – 1859 & QG2 - 1860**
BBS preview bug has been fixed.
- 4. RRCP – 1277**
For File to file copy use library option
- 5. RRCP - 1214**
Multirange callout not deleting bug has been fixed.
- 6. RRCP - 1203 / QG2 – 1766 & QG2 - 1767**
Release order coating bus has been fixed.
- 7. RRCP - 1197 / QG2 – 1760 & QG2 - 1761**
Multi range callout bug has been fixed.
- 8. RRCP - 1282 / QG2 – 1911 & QG2 – 1912**
Rebar spread bug has been fixed
- 9. RRCP -1281 / QG2 – 1913 & QG2 – 1914**
Match property problem has been resolved
- 10. RRCP - 1280 / QG2 – 1915 & QG2 – 1916**
Undo & Redo command has been fixed
- 11. RRCP - 1277**
Use Library option to avoid file to file copy problem
- 12. RRCP - 1289 / QG2 – 1938 & QG2 – 1939**
Quantity and spacing issue has been fixed
- 13. RRCP - 1298 / QG2 – 1952 & QG2 – 1953**
Blocking of coupler/thread bend of calloutonlybendtype was fixed.
- 14. RRCP - 1300 / QG2 – 1958 & QG2 – 1959**
Editing of image lable (to change size, format) was fixed.