

Version 4.0.20.20




RGS REBAR

Release NOTE – NOVEMBER 2023

New Features

1. RRCP - 1311 / QG2 – 1989 & QG2 – 1990

A New checkbox provided to Remove the bar Coating abbreviation in Takeoff





The screenshot shows the 'Take off' dialog box with the following details:

- TakeOff Details:** Takeoff Format: CSF
- Job Details:** Client Job No.: A23-100, Detailing Code: CSA, Job Name: HIGH PLANS, Drawing No.: , Customer Name: LEESWOOD, Revision No.: , Job Location: ONTARIO, Prepared By: , Description 1: , Prepared Date: 14-11-2023, Description 2: , Checked By: , Control Code: , Checked Date: 14-11-2023, Release No.: , Reference: , Bid Item: , SAC Code: , Excuse Code: .
- Selection Method:** Use Existing Control Code, Select Bars & Callouts, Include Bar Labels in selection, Select Element Marks, Include Bar Views in selection, New Selection, Add Entities, Remove Entity. Selected Color: [Green].
- Sorting Type:** Type 1, Type 2. Bar mark format: Bar Mark format in Reports 01a.
- Options:** ADD VERSION, ADD REMARKS, ADD SPACELINE, EXTENDED.

2. RRCP - 1312 / QG2 – 1991 & QG2 – 1992


Use **CHANGEALPHACODE** command to Use the Double AlphaCode



The screenshot shows the 'Global Change - AlphaCo...' dialog box. The 'New Alphacode For A' field contains the text 'AB'. The 'OK' and 'Cancel' buttons are visible at the bottom.


3. RRCP - 1346 / QG2 – 2008 & QG2 - 2009

The Image label can be shown in **Findcalloutorbar** command



4. RRCP - 1344 / QG2 – 2004 & QG2 - 2005

A New option added in **audit drawing** command to check **Standard hook values**



5. RRCP - 1305 / QG2 – 1968 & QG2 - 1969

BBSVIEW command option given to show required bbs format

| Cat Length | ItemCode | No | Dia | Stirrup Or. | Hook Val. | Hook Val. | Alpha Code | Alias | Area Four | Bar Dia | Bar Locat. | Bar Mark | Bar No |
|------------|----------|------|---------|-------------|-----------|-----------|------------|-------|-----------|---------|------------|----------|--------|
| B | B | 2.25 | Hook | 6 | 4 | 5 | A | | 30' 30" | 0.375 | | | |
| A#C-D#E | A#C | 2.25 | Hook | 6 | 4 | 5 | A | | 12' 00" | 0.375 | 3,1203 | 3,12 | |
| A#B | A#B | 2.25 | Hook | 6 | 4 | 5 | A | | 12' 00" | 0.375 | 3,1203 | 3,12 | |
| A#B-C-D | A#B-C-D | 2 | Stirrup | 4.5 | 4.5 | 5 | A | | 2' 00" | 0.375 | 37234 | 3723 | |
| A#B-C | A#B-C | 2.25 | Hook | 6 | 4 | 5 | A | | 12' 00" | 0.375 | 3,1203 | 3,12 | |
| A#C-D-E | A#C-D-E | 2.25 | Hook | 6 | 4 | 5 | A | | 2' 00" | 0.375 | 3,1203 | 3,12 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3001 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3002 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3003 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3004 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3005 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3006 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3007 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3008 | 300 | |
| B | B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3009 | 300 | |
| A#B | A#B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3010 | 301 | |
| A#B | A#B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3011 | 301 | |
| A#B | A#B | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3012 | 301 | |
| A#B-C-D | A#B-C-D | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3013 | 301 | |
| A#C-D-E | A#C-D-E | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3014 | 301 | |
| A#C-D-E | A#C-D-E | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3015 | 301 | |
| A#C-D-E | A#C-D | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3016 | 301 | |
| A#B-C-D | A#B-C-D | 3.75 | Hook | 10 | 5.5 | 7 | A | | 2' 00" | 0.425 | 3017 | 301 | |
| A#B-C-D | A#B-C-D | 1.75 | Hook | 10 | 4.4 | 7 | A | | 2' 00" | 0.425 | 3018 | 301 | |

| ITEM | MBRK | No | Pro | Size | Length | Type | A | B | C | D | E | F | G | H | J | K | O | R |
|------|---------|----|-----|-------------|--------|------------|------------|---------|--------|---------|--------|---|------------|---|---|---|---|---|
| 1 | | 1 | 1# | 10'-10" | 8 | | | 10'-10" | | | | | | | | | | |
| 2 | 31115B | 1 | 1# | 12'-00" | 17 | | 1'-00" | 11'-00" | | | | | | | | | | |
| 3 | 311201 | 1 | 1# | 12'-00" | 2 | 0'-00" | 12'-00" | | | | | | | | | | | |
| 4 | 372424 | 1 | 1# | 8'-06 1/2" | T1 | 0'-04 1/2" | 2'-00" | 2'-00" | 2'-00" | 2'-00" | | | 0'-04 1/2" | | | | | |
| 5 | 30,000B | 1 | 1# | 12'-00" | 2 | 2'-00" | 10'-00" | | | | | | | | | | | |
| 6 | 30,010F | 1 | 1# | 16'-11 1/2" | 13 | | 2'-00" | | | 11'-00" | 2'-00" | | | | | | | |
| 7 | 5001 | 1 | 1# | 2'-00" | 0.50 | | 2'-00" | | | | | | | | | | | |
| 8 | 5002 | 1 | 1# | 2'-00" | 0.50 | | 2'-00" | | | | | | | | | | | |
| 9 | 5003 | 1 | 1# | 3'-04 1/2" | 0.50 | | 3'-04 1/2" | | | | | | | | | | | |
| 10 | 5004 | 1 | 1# | 2'-04 1/2" | 0.50 | | 2'-04 1/2" | | | | | | | | | | | |
| 11 | 5005 | 1 | 1# | 3'-00" | 0.50 | | 3'-00" | | | | | | | | | | | |

Bug

1. RRCP - 891 / QG2 – 845 & QG2 - 846

Callout disappearing bug has resolved once place callout and can give CB command

2. RRCP - 1314 / QG2 – 1998 & QG2 - 1999

Image Label moving left side bug has resolved

3. RRCP - 1301 / QG2 – 1964 & QG2 - 1966

Bar mark issue has resolved

4. RRCP - 1352 / QG2 – 2029 & QG2 - 2030

Library issue has resolved